

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,906,564 B2
DATED : June 14, 2005
INVENTOR(S) : Kwang Y. Kim

Page 1 of 1


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10.

Line 41, "coupling a first resistor between the a first output terminal" should appear as
-- coupling a first resistor between the first output terminal --.
Line 49, "coupling a second clock buffer devices" should appear as -- coupling a second
clock buffer device --.

Signed and Sealed this

Sixth Day of September, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office